

# Oil Field Environmental Incident Summary

**Incident:** 20140614154650      **Date/Time of Notice:** 06/14/2014 15:46

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:** ONEOK ROCKIES MIDSTREAM

**Well Name:** Stateline Compressor Station

**Field Name:**

**Well File #:**

**Date Incident:** 6/13/2014

**Time Incident:** 16:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 102

**Sec:** 10

**Qtr:**

**Location Description:** 14312 59th Street NW  
Williston, ND 58801

**Submitted By:** Jason Lyons

**Received By:**

**Contact Person:** Jason Lyons  
2700 Lincoln Ave.  
Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	11	Barrels	11	Barrels		

**Description of Other Released Contaminant:**

Natural Gas Liquids (Condensate)

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There were no immediate risks to human health or the environment.

**Areal Extent:**

Incident contained on facility site. A 40 sq. ft. area was impacted outside the containment dike.

**Potential Environmental Impacts:**

There were no environmental impacts beyond facility soil.

**Action Taken or Planned:**

A vac truck removed the 10.0 bbls contained within the dike and the fluid was reintroduced back into Tank #1. One (1.0) bbl of fluid impacted the soil outside of the dike. This soil was removed via roustabout crew and staged on-site for removal. Soil samples were collected and shipped to a certified lab. The impacted soil will be removed following receipt of analytical results.

**Wastes Disposal Location:** The liquids were reintroduced back into the facility storage tank (Tank #1). The impacted soil will be disposed at an approved landfill following receipt of analytical results.

**Agencies Involved:** Mike Hallesy - Williams County LEPC

**Updates**

---

**Date:** 6/16/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill occurred at a facility that is not under NDIC jurisdiction. Followup is necessary.

---

**Date:** 4/2/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

4/2/2015 at 13:54, on location. Staining visible on liner within secondary containment around tanks on north side of facility. Some staining on gravel/scoria also visible outside but directly adjacent to the containment. It does not appear to be able to migrate offsite. Called in to report contact and left a message to discuss.

---

**Date:** 5/5/2015      **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Email from contact with the responsible party. According to contact, the small spills outside of the containment were "likely unrelated" to the reported spill, but the spills were cleaned up regardless. Photos showing the remediated areas were supplied by the contact. No further followup required.